NTEK北测 NSTL

Test Report

Report No.: DGC250507007PE06

Page 1 of 4

ApplicantGOLDEN APPLEXX CO., INC.Address19805 HARRISON AVE, INDUSTRY, CA 91789

The following sample(s) was/were submitted and identified on behalf of the client as:

Product Name: Heavy Duty Golf Divot Fixer Repair ToolSKU: DVTFIX12

Date of Sample Received: May 07, 2025Test period: May 07, 2025 - May 13, 2025

Test requested

As specified by client, with reference to California Proposition 65, to determine the total Lead content on submitted sample.

Test method

: Please refer to next page.

Test result

: Please refer to next page.

Approved by:

Richard Ke (Signed for and on behalf)

Kichand

May 13, 2025

 Dongguan NTEK Testing Technology Co., Ltd.

 Address: Building 3, Meisaidaxin Park, Keji 8th Road, Songshan Lake High-Tech Industrial Development Zone, Dongguan, Guangdong, China

 Tel: (+86-769) 23301666
 Fax: (+86-769) 23301600

 Email: service@gdntek.cn
 http://www.dgntek.org.cn



NTEK北测 NSTL

Test Report

Report No.: DGC250507007PE06

Page 2 of 4

Test results:

Test Item	Test method	Unit	MDL	Result No.1
	With reference to	2		
Total Lead (Pb)	CPSC-CH-E1001-08.3,	mg/kg	2 2	N.D.
	tested by ICP-OES	5		


Test Part Description:

Group No.	Picture No.	Test Part Name	L'	
No.1	6	Silver metal		4

Note:

- (1) mg/kg=ppm=0.0001%;
- (2) N.D.=Not Detected(<MDL);
- (3) MDL=Method Detection Limit;
- (4) The Client specified material test.
- (5) Unless otherwise specified, refer to ILAC-G8:09/2019 and use the binary decision rule of simple acceptance (W=0) for conformity assessment.

Operation Flow Chart:



Dongguan NTEK Testing Technology Co., Ltd.

Address: Building 3, Meisaidaxin Park, Keji 8th Road, Songshan Lake High-Tech Industrial Development Zone, Dongguan, Guangdong, China Tel: (+86-769) 23301666 Fax: (+86-769) 23301600 Email: service@gdntek.cn http://www.dgntek.org.cn

NTEK北测 NSTL

Test Report

Report No.: DGC250507007PE06

Photograph of Sample:

Page 3 of 4



 Dongguan NTEK Testing Technology Co., Ltd.

 Address: Building 3, Meisaidaxin Park, Keji 8th Road, Songshan Lake High-Tech Industrial Development Zone, Dongguan, Guangdong, China

 Tel: (+86-769) 23301666
 Fax: (+86-769) 23301600
 Email: service@gdntek.cn
 http://www.dgntek.org.cn

NYEK北测 NSTL

Test Report

Report No.: DGC250507007PE06

声明: Statement:

1.检测报告无批准人签字、"检测专用章"或"报告章"无效;

1. This report is considered invalid without approved signature, Detection special seal or Report seal; 2. 样品及样品信息由申请者提供,申请者应对其真实性负责,NTEK 未核实其真实性;

2. The sample(s) and sample information was/were provided by the client who should be responsible for the authenticity which NTEK hasn't verified;

3. 本报告检测结果仅对受测样品负责;

3. The result(s) shown in this report refer(s) only to the sample(s) tested;

4. 未经 NTEK 书面同意,不得部分复制本报告。

4. Without written approval of NTEK, this report can't be reproduced except in full;

5. 如检测报告中的英文内容与中文内容有差异,以中文为准。

5. In case of any discrepancy between the English version and Chinese version of the testing reports (if generated), the Chinese version shall prevail.

备注:报告未加盖 CMA 资质章时,本报告中的数据结果供科研、教学、企业内部质量控制、企业产品研发 等目的用。

Remark: When the report without CMA qualification seal, the testing data and result(s) in this report is(are) just for scientific research, education, internal quality control and product development etc.

End of Report

 Dongguan NTEK Testing Technology Co., Ltd.

 Address: Building 3, Meisaidaxin Park, Keji 8th Road, Songshan Lake High-Tech Industrial Development Zone, Dongguan, Guangdong, China

 Tel: (+86-769) 23301666
 Fax: (+86-769) 23301600
 Email: service@gdntek.cn
 http://www.dgntek.org.cr
 Page 4 of 4